



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program July 21, 2011

Reviewed: JK

<b>Mine Name:</b> County Canyon Shale	<b>Permit Number:</b> M/023/0024
<b>Operator Name:</b> Ash Grove Cement Company	<b>Inspection Date:</b> July 14, 2011
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 12:45 -1:00 pm
<b>Other Participants:</b> Josh Neilsen	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This was a courtesy inspection at the Permittee's request.

#### Inspection Summary:

The Permittee had questions about doing exploration work near the mine site. The Division and the Permittee discussed the permitting process.

#### Conclusions and Recommendations:

The Division should assist the Permittee as needed.

**Inspector's Signature**


WHW

cc: (OPERATOR)

Jerry Mansfield BLM

O:\M023-Juab\M0230024-CountyCanyon\Inspection\Insp-07142011.doc





Stockpile



Area where exploration could take place.